





FEDERAL EXPRESS

September 30, 1999

RCRA RECORDS CLIVE FACILITY MACNERIO I.D. NO. CIDOCHIC 4599
FILE LOC. R-13
OTHER ROME # 100830



RDMS DocID

00100830

Ms. Marina Crawford
Waste Engineering and Enforcement Division
Bureau of Waste Management
Connecticut Department of Environmental Protection
79 Elm Street
Hartford, Connecticut 06106-5127

RE: RCRA CORRECTIVE ACTION ENVIRONMENTAL INDICATOR CHECKLIST, MacDERMID, INC., 526 HUNTINDGON AVENUE, WATERBURY, CONNECTICUT (HRP #MAC0026.CA)

Dear Ms. Crawford:

Enclosed for your review is the completed RCRA Corrective Action Environmental Indicator (EI) Checklist for the MacDermid, Inc. facility located at 526 Huntingdon Avenue in Waterbury, Connecticut (EPA ID #CTD001164599). As indicated in this checklist, it was HRP Associates' opinion that the "IN" status code applied to both Els due to the limited environmental data available for review.

If you have any questions or require additional information, please do not hesitate to contact HRP at (860) 793-6899.

Sincerely.

HRP ASSOCIATES, INC.

Richard D. McFee, P.E.

Associate

Enclosure RDM/db

CC:

Greg Strong, MacDermid, Inc.

RECEIVED

OCT 01 1999

THE WAY OF SHARE AND A SHARE SHEET OF SHEET SHEE

DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION

Interim Final 2/5/99

RCRA Corrective Action Environmental Indicator (EI) RCRIS code (CA750)

Migration of Contaminated Groundwater Under Control

Facility	Name:	MacDermid, Inc.				
Facility	Address:	526 Huntingdon Avenue, Waterbury, CT 06708				
Facility	EPA ID#:	CTD001164599				
1.	Has all available relevant/significant information on known and reasonably suspected releases to groundwater media, subject to RCRA Corrective Action (e.g. from Solid Waste Management Unit (SWMU). Regulated Units (RU), and Areas of Concern (AOC), been considered in this EI determined to the contraction of the contra					
		If yes – check here and continue with #2 below.				
		If no -re-evaluate existing data, or				
		If data are not available, skip to #8 and enter "IN" (more information needed) status code				

BACKGROUND

Definition of Environmental Indicators (for the RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Migration of Contaminated Groundwater Under Control" EI

A positive "Migration of Contaminated Groundwater Under Control" EI determination ("YE" status code) indicates that the migration of "contaminated" groundwater has stabilized, and that monitoring will be conducted to confirm that contaminated groundwater remains within the original "area of contaminated groundwater" (for all groundwater "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA. The "Migration of Contaminated Groundwater Under Control" EI pertains ONLY to the physical migration (i.e., further spread) of contaminated groundwater and contaminants within groundwater (e.g., non-aqueous phase liquids or NAPLs). Achieving this EI does not substitute for achieving other stabilization or final remedy requirements and expectations associated with sources of contamination and the need to restore, wherever practicable, contaminated groundwater to be suitable for its designated current and future uses.

Duration/Applicability of EI Determinations

EI determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

2.	Is groundwater known or reasonably suspected to be "contaminated" above appropriately protective "levels" (i.e., applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action, anywhere at, or from, the facility?
	If yes – continue after identifying key contaminants, citing appropriate "levels" and referencing supporting documentation.
	If no – skip to #8 and enter "YE" status code, after citing appropriate "levels" and referencing supporting documentation to demonstrate that groundwater is not "contaminated."
	_✓ If unknown – skip to #8 and enter "IN" status code.
	Rationale and Reference(s): Nineteen (19) specific areas of concern (AOCs) have been identified at the MacDermid, Inc. facility located at 526 Huntingdon Avenue in Waterbury, Connecticut. Five (5) of these AOCs have been selected due to past releases and/or their high potential for release. Although releases at the site are known to have occurred there is no analytical documentation available to confirm nor refute the presence of contaminated groundwater at the site. A detailed description of each AOC is provided in Attachment A.

Footnotes:

¹"Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriate "levels" (appropriate for the protection of the groundwater resource and its beneficial uses).

	ed to rema	n of contaminated ground water stabilized (such that contaminated groundwater is ain within "existing area of contaminated groundwater" as defined by the monitoring ated at the time of this determination)?
		If yes – continue, after presenting or referencing the physical evidence (e.g., grounds sampling/measurement/migration barrier data) and rationale why contaminated groundwater is expected to remain within the (horizontal or vertical) dimensions of t "existing area of ground water contamination" ²).
		If no (contaminated groundwater is observed or expected to migrate beyond the designated locations defining the "existing area of groundwater contamination" - sk #8 and enter "NO" status code, after providing an explanation.
	_	If unknown – skip to #8 and enter "IN" status code.
Ration	ale and R	eference(s):
Tution	aro arra re	orerenee(s).

²"existing area of contaminated groundwater" is an area (with horizontal and vertical dimensions) that has been verifiably demonstrated to contain all relevant groundwater contamination for this determination, and is defined by designated (monitoring) locations proximate to the outer perimeter of "contamination" that can and will be sampled/tested in the future to physically verify that all "contaminated" groundwater remains within this area, and that the further migration of "contaminated" groundwater is not occurring. Reasonable allowances in the proximity of the monitoring locations are permissible to incorporate formal remedy decisions (i.e., including public participation) allowing a limited area for natural attenuation.

Does	"contaminated" groundwater discharge into surface water bodies?
	If yes – continue after identifying potentially affected surface water bodies.
	If no – skip to #7 (and enter a "YE" status code in #8, if #7 = yes) after providing ar explanation and/or referencing documentation supporting that groundwater
	_✓ If unknown – skip to #8 and enter "IN" status code.
Ratio	nale and Reference(s):
	- And the state of

5.	Is the discharge of "contaminated" groundwater into surface maximum concentration of each contaminant discharging in appropriate groundwater "level" and there are no other condidischarging contaminants, or environmental setting), which sunacceptable impacts to surface water, sediments, or eco-sys	to surface water is less than 10 times their tions (e.g., the nature, and number, of significantly increase the potential for
	the maximum known or reasonably suspec discharged above their groundwater "level there is evidence that the concentrations ar professional judgement/explanation (or ref	"the value of the appropriate "level(s)," and if e increasing; and 2) provide a statement of erence documentation) supporting that the to the surface water is not anticipated to have
	significant) – continue after documenting: suspected concentration ³ of <u>each</u> contamin the value of the appropriate "level(s)," and increasing; and 2) for any contaminants di greater than 100 times their appropriate gr (mass in kg/yr) of each of these contamina	ant discharged above its groundwater "level," if there is evidence that the concentrations are scharging into surface water in concentrations oundwater "levels," the estimated total amount ints that are being discharged (loaded) into the rmination), and identify if there is evidence
	✓ If unknown – enter "IN" status code in #8.	
	Rationale and Reference(s):	

³ As measured in groundwater prior to entry to the groundwater-surface water/sediment interaction (e.g., hyporheic) zone.

(i.e., not cause in	ge of "contaminated" groundwater into surface water be shown to be "currently acceptable" inpact to surface water, sediments or eco-systems that should not be allowed to continue edy decision can be made and implemented ⁴)?
	If yes — continue after either: 1) identifying the Final Remedy decision incorporating these conditions, or other site-specific criteria (developed for the protection of the site's surface water, sediments, and eco-systems), and referencing supporting documentation demonstrating that these criteria are not exceeded by the discharging groundwater, OR 2) providing or referencing an interim-assessment, ⁵ appropriate to the potential for impact, that shows the discharge of groundwater contaminants into the surface water is (in the opinion of a trained specialists, including ecologist) adequately protective of receiving surface water, sediments, and eco-systems, until such time when a full assessment and final remedy decision can be made. Factors which should be considered in the interim-assessment (where appropriate to help identify the impact associated with discharging groundwater) include: surface water body size, flow, use/classification/habitats and contaminant loading limits, other sources of surface water/sediment contamination, surface water and sediment sample results and comparisons to available and appropriate surface water and sediment "levels," as well as any other factors, such as effects on ecological receptors (e.g., via bio-assays/benthic surveys or site-specific ecological Risk Assessments), that the overseeing regulatory agency would deem appropriate for making the EI determination.
	If no – (the discharge of "contaminated" groundwater cannot be shown to be "currently acceptable") –skip to #8 and enter "NO" status code, after documenting the currently unacceptable impacts to the surface water body, sediments, and/or eco-systems.
<u> </u>	If unknown – skip to 8 and enter "IN" status code.
Rationale and R	eference(s):
	areas of inflowing groundwater can be critical habitats (e.g., nurseries or thermal refugia) is, appropriate specialist (e.g., ecologist) should be included in management decisions that
could eliminate	these areas by significantly altering or reversing groundwater flow pathways near surface

water bodies.

⁵ The understanding of the impacts of contaminated groundwater discharges into surface water bodies is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration to be reasonably certain that discharges are not causing currently unacceptable impacts to the surface waters, sediments or eco-systems.

7.	Will groundwater monitoring / measurement data (and surface water/sediment/ecological data, as necessary) be collected in the future to verify that contaminated groundwater has remained within the horizontal (or vertical, as necessary) dimensions of the "existing area of contaminated groundwater?"					
	If yes – continue after providing or citing documentation for planned activities or future sampling/measurement events. Specifically identify the well/measurement locations which will be tested in the future to verify the expectation (identified in #3) that groundwater contamination will not be migrating horizontally (or vertically, as necessary) beyond the "existing area of groundwater contamination."					
	If no – enter "NO" status code in #8.					
	✓ If unknown – enter "IN" status code in #8.					
	Rationale and Reference(s):					

8.	Check the appropriate RCRIS status codes for the Migration of Contaminated Groundwater Under Control EI (event code CA750), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).					
	-	YE - Yes, "Migration of Contaminated Groundwater Under Control" has been verified. Based on a review of the information contained in this EI determination, it has been determined that the "Migration of Contaminated Groundwater" is "Under Control" at the				
		facility, EPA	ID#	, located		
		atindicates that the migration of "contamin	. Specifically, this deteri	nination		
		indicates that the migration of "contamin	nated" groundwater is under	control, and that		
		monitoring will be conducted to confirm	that contaminated groundw	ater		
		remains within the "existing area of con	taminated groundwater". Th	is		
		determination will be re-evaluated when	the Agency becomes aware	of		
		significant changes at the facility.				
		NO – Unacceptable migration of contan	ninated groundwater is obser	ved or expected.		
	<u> </u>	IN – More information is needed to make	te a determination.			
	Completed by	(signature)	Date	_		
	•	(print)				
		(title)				
	Supervisor	(signature) (print) (title) (EPA Region or State)				
	Locations where References may be found:					
		RCRA Facility Assessment, TRC Enviro onmental Indicators Review, CT Departm		tion		
						
		The state of the s				
	-					
	Contact telepho	ne and e-mail numbers				
	f					
		(name) Richard D. McFee, P.E.	**************************************			
		(phone #) (860) 793-6899				
		(e-mail) hrp6@ntplx.net				

DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION

Interim Final 2/5/99

RCRA Corrective Action Environmental Indicator (EI) RCRIS code (CA725)

Current Human Exposures Under Control

racinty	Name:	MacDermid, inc.
Facility	Address:	526 Huntingdon Avenue, Waterbury, Connecticut 06708
Facility	EPA ID #:	CTD001164599
1.	groundwater, surfa	elevant/significant information on known and reasonably suspected releases to soil, ace water/sediments, and air, subject to RCRA Corrective Action (e.g. from Solid Waste s (SWMU), Regulated Units (RU), and Areas of Concern (AOC), been considered in ion?
	<u> </u>	If yes – check here and continue with #2 below.
		If no -re-evaluate existing data, or
		If data are no available skip to #6 and enter "IN" (more information needed) status code.

BACKGROUND

Definition of Environmental Indicators (for the RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Current Human Exposures Under Control" EI

A positive "Current Human Exposures Under Control" El determination ("YE" status code) indicates that there are no "unacceptable" human exposures to "contamination" (i.e., contaminants in concentrations in excess of appropriate risk-based levels) that can be reasonably expected under current land- and groundwater-use conditions (for all "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA. The "Current Human Exposures Under Control" EI are for reasonably expected human exposures under current land- and groundwater-use conditions ONLY, and do not consider potential future land- or groundwater-use conditions or ecological receptors. The RCRA Corrective Action program's overall mission to protect human health and the environment requires that Final remedies address these issues (i.e., potential future human exposure scenarios, future land and groundwater uses, and ecological receptors).

Duration/Applicability of EI Determinations

EI determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

Are groundwater, soil, surface water, sediments, or air media known or reasonably suspected to be

Groundwater	<u>Yes</u>	<u>No</u>	?	Rationale / Key Contaminants Refer to Attachment A
Air (indoors) ²			✓	
Surface Soil (e.g., <2 ft)			✓	Refer to Attachment A
Surface Water			<u> </u>	
Sediment			<u> </u>	
Subsurf. Soil (e.g., >2 ft)			<u> </u>	Refer to Attachment A
Air (outdoors)			<u> </u>	
If yes ("contar determ	for any i ninated' ination t	media) – '' medium	n, citing a nedium co	after identifying key contaminants in each
If yes ("contar determ support ✓ If unkn	for any minated' ination ting doc	media) – " medium that the m umentation	continue n, citing a nedium co on. edia) skip	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for ould pose an unacceptable risk), and referencing to #6 and enter "IN" status code.
☐ If yes ("contar determs support ✓ If unkn Rationale and Reference(for any minated' ination to the cing docurrent own (for section of the cing of the cing own (for section own (for section own (for section of the cing	media) – " medium that the m umentation or any me	continue n, citing a nedium co on. edia) skip	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility	for any minated' ination to the cing docum (for section of the cing of the cin	media) – " medium that the m umentation or any me eteen (19 d at 526 J	continue n, citing a nedium co on. dia) skip y specific Huntingdo	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Careas of concern (AOCs) have been identified at to Avenue in Waterbury, Connecticut. Although
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be	for any minated' ination ting docum (foo work) (s): Nin y located en rem	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved fror	continue n, citing a nedium co on. edia) skip 0) specific Huntingdon three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. c areas of concern (AOCs) have been identified at to Avenue in Waterbury, Connecticut. Although to of the AOCs, there is no analytical documentation.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at the contamination of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be available to confirm nor	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at the contamination of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be available to confirm nor	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at the contamination of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be available to confirm nor	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for build pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at to Avenue in Waterbury, Connecticut. Although to of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be available to confirm nor	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for buld pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at the contamination of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.
If yes ("contar determing support ✓ If unkn Rationale and Reference(MacDermid, Inc. facility contaminated soil has be available to confirm nor	for any minated' ination to ing document of the following for the	media) – " medium that the m umentation or any me eteen (19 d at 526 l oved from that there	continue n, citing a nedium co on. edia) skip nedia) specific Huntingdo n three (3	after identifying key contaminants in each ppropriate "levels" (or provide an explanation for to build pose an unacceptable risk), and referencing to #6 and enter "IN" status code. Exarcas of concern (AOCs) have been identified at to Avenue in Waterbury, Connecticut. Although to of the AOCs, there is no analytical documentation inacceptable" human exposures to contamination.

Footnotes:

2.

¹ "Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriately protective risk-based "levels" (for the media, that identify risks within the acceptable risk range).

² Recent evidence (from the Colorado Dept. of Public Health and Environment, and others) suggest that unacceptable indoor air concentrations are more common in structures above groundwater with volatile contaminants than previously believed. This is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration necessary to be reasonably certain that indoor air (in structures located above (and adjacent to) groundwater with volatile contaminants) does not present unacceptable risks.

Summary Exposure Pathway Evaluation Table				
Gro Air	Residents Workers Day-Care Construction Trespassers Recreation Food and water indoors) (surface, e.g., <2 ft)			
Surf Sedi	cace Water			
	outdoors)			
Inst	uctions for Summary Exposure Pathway Evaluation Table:			
	1. Strike-out specific Media including Human Receptors ³ spaces for Media which are not "contaminated") as identified in #2 above.			
	2. enter "yes" or "no" for potential "completeness" under each "Contaminated" Media – Human Receptor combination (Pathway).			
Med com	e: In order to focus the evaluation to the most probable combinations some potential "Contaminated" ia – Human Receptor combinations (Pathways) do not have check spaces (""). While these binations may not be probable in most situations they may be possible in some settings and should be do as necessary.			
	If no (pathways are not complete for any contaminated media-receptor combination) – skip to #6, and enter "YE" status code, after explaining and/or referencing condition(s) in-place, whether natural or man-made, preventing a complete exposure pathway from each contaminated medium (e.g., use optional <u>Pathway Evaluation Work Sheet</u> to analyze major pathways).			
	If yes (pathways are complete for any "Contaminated" Media – Human Receptor combination) – continue after providing supporting explanation.			
	If unknown (for any "Contaminated" Media – Human Receptor combination) – skip to # and enter "IN" status code.			
Rat	onale and Reference(s):			

4.	Can the exposures from any of the complete pathways identified in #3 be reasonably expected to be "significant" (i.e., potentially "unacceptable" because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable "levels" (used to identify the "contamination"); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable "levels") could result in greater than acceptable risks)?
	If no (exposures can not be reasonably expected to be significant (i.e., potentially "unacceptable") for any complete exposure pathway) – skip to #6 and enter "YE" status code after explaining and/or referencing documentation justifying why the exposures (from each of the complete pathways) to "contamination" (identified in #3) are not expected to be "significant."
	If yes (exposures could be reasonably expected to be "significant" (i.e., potentially "unacceptable") for any complete exposure pathway) – continue after providing a description (of each potentially "unacceptable" exposure pathway) and explaining and/or referencing documentation justifying why the exposures (from each of the remaining complete pathways) to "contamination" (identified in #3) are not expected to be "significant."
	If unknown (for any complete pathway) – skip to #6 and enter "IN" status code.
	Rationale and Reference(s):
4	

⁴ If there is any question on whether the identified exposures are "significant" (i.e., potentially "unacceptable") consult a human health Risk Assessment specialist with appropriate education, training and experience.

site-specific Human Health Risk Assessment).	Can the "significant" exposures (identified in #4) be shown to be within acceptable limits?		
continue and enter "NO" status code after providing a description of each potentially "unacceptable" exposure. If unknown (for any potentially "unacceptable" exposure) – continue and enter "IN" status code.	 continue and enter "YE" after summarizing and referencing documentation justifying why all "significant" exposures to "contamination" are within acceptable limits (e.g., a		
status code.			
Rationale and Reference(s):			

5 .	Check the appropriate RCRIS status codes for the Current Human Exposures Under Control EI (event code CA725), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (attach appropriate supporting documentation as well as a map of the facility).				
		YE - Yes, "Current Human Exposures Under review of the information contained in this EI Exposures" are expected to be "Under Controlacility, EPA ID # under current and determination will be re-evaluated when the A significant changes at the facility.	Determination, "Current Human " at the, located at reasonably expected conditions. This		
		NO – "Current Human Exposures" are NOT "	Under Control."		
		IN – More information is needed to make a de	etermination.		
	Completed by	(signature) (print) (title)	Date		
	Supervisor	(signature) (print) (title) (EPA Region or State)	Date		
	Locations wher	Locations where References may be found:			
		Final RCRA Facility Assessment, TRC Environmental Corporation Environmental Indicators Review, CT Department of Environmental Protection			
	Contact telepho	ne and e-mail numbers			
		(name) Richard D. McFee, P.E. (phone #) (860) 793-6899			

FINAL NOTE: THE HUMAN EXPOSURES EI IS A QUALITATIVE SCREENING OF EXPOSURES AND THE DETERMINATIONS WITHIN THIS DOCUMENT SHOULD NOT BE USED AS THE SOLE BASIS FOR RESTRICTING THE SCOPE OF MORE DETAILED (E.G., SITE-SPECIFIC) ASSESSMENTS OF RISK.

(e-mail) hrp6@ntplx.net

Areas of Concern Page 1

Nineteen (19) areas of concern (AOCs) have been identified at the MacDermid, Inc. site located at 526 Huntingdon Ave., Waterbury, Connecticut. The general location of each AOC is shown on Figure 1. Each AOC is been briefly described below.

AOC #1: Metal Hydroxide Sludge and Waste Lagoon

Description:

This 50' by 95' area, located on the opposite side of Huntingdon Avenue on MacDermid property, was used as a disposal lagoon for approximately 1000 yd³ of unspecified organic and inorganic wastes in 1978. The sludge and soil wastes originated from two (2) lagoons which received process wastes. The lagoon was also used to receive metal hydroxide sludge from MacDermid's new WWTS which could contain chromium, lead, copper, nickel, iron, silver and cyanide.. An asphalt cap was installed in 1986 to prevent surface water from percolating through the former lagoon (TRC, 1993).

Known or

Suspected Releases: In 1982-1983 approximately 168 yd³ of sludge and soil were removed and disposed off-site. This unlined lagoon, created in 1978, was not capped until 1986. Documentation of confirmatory sampling upon capping the lagoon is not available (CTDEP, 1998). In 1993, TRC reported that cracks present in the asphalt may continue to allow surface water to penetrate the lagoon.

AOC #2: Former Waste Lagoons

Description:

This area is located on the east side of the Huntingdon Avenue building. From circa 1930 to 1978 the organic and inorganic waste lagoons mentioned above were used to dispose of MacDermid's process wastes (CTDEP, 1998). Sludge and soil from these lagoons was excavated in 1978 and deposited into AOC #1. The area is presently completely paved with asphalt.

Known or

Suspected Releases: On October 1, 1992, limited groundwater monitoring data from wells located near the lagoons showed elevated concentrations of chromium, copper and nickel. The levels were greater than the standards established in the Connecticut Remediation Standard Regulations (RSR) for surface water protection and groundwater protection for GA areas (CTDEP, 1998).

Areas of Concern Page 2

AOC #3: Ink Spill Area

Description:

This AOC is located outside the north end of the Gear Street building. Discovered in 1987 by IPC personnel, the area received ink waste from a leak in the former collection sump. The wastes released in this area included pigments, solvents, anilines, resins, and polymers used in ink blending (TRC, 1993). The area is presently located beneath a concrete pad.

Known or

Suspected Releases: Various wastes were released from a leak in the former collection sump. After discovery and inspection of the stained area, approximately 550 ft³ of contaminated soil containing elevated levels of toluene, 1,1,1trichloroethane, ethyl benzene and xylene were excavated (CTDEP. 1998). An investigation of the groundwater in the area was not conducted. Information regarding the volume, toxicity and mobility of the wastes at this location is not available (TRC, 1993).

AOC #4: Underground Storage Tanks (UST)

Description:

A 5.000-gallon heating oil UST and a 10.000-gallon fuel oil UST are located on the north side and east side of the Huntingdon Avenue respectively. The fuel oil UST is presently empty while the heating oil UST is currently in use. A yearly tightness test is conducted on the tanks (TRC, 1993).

Known or

Suspected Releases: There is no documentation of a release from either of these USTs (TRC, 1993).

AOC #5: Transformer Vault

Description:

A 4'x4'x4' steel transformer vault is located on a concrete pad outside

the south side of the Gear Street building (TRC, 1993).

Known or

Suspected Releases: There are no documented releases concerning this AOC (TRC, 1993).

Areas of Concern Page 3

AOC #6: Wastewater Treatment System (WWTS)

Description:

The WWTS located in the southwest corner of the Huntingdon Avenue building was installed in 1978. The system consists of 13 treatment tanks, a filter press and a metal hydroxide sludge roll-off dumpster (CTDEP, 1998). Copper etchant, solder stripper, electroless-nickel and spills from dry chemical blending areas and hazardous waste storage areas are treated in the WWTS (TRC, 1993). Treated wastewater is ultimately discharged to the Waterbury Sewage Treatment Plant. As of May 1998, four (4) new treatment tanks with secondary containment have been installed and operation and maintenance of the WWTS has improved (CTDEP, 1998).

Known or

Suspected Releases: According to CTDEP files, the WWTS tanks have leaked on several occasions. On January 28, 1991, 7,000 gallons of wastewater were released from a holding tank and entered the Naugatuck River. Additional information regarding this spill is not available. November 1994, a 1,500 gallon spill of a copper etchant solution was also released into the Naugatuck River (CTDEP, 1998).

AOC #7: Dry Chemical Silos

Description:

Four (4) 10,000-gallon steel silos are located on a concrete pad outside the east side of the Huntingdon Avenue building. The silos were formerly used for the storage of dry sodium carbonate, sodium metasilicate, sodium hydroxide and sodium hydrogen sulfate. They are currently empty and are scheduled to be removed from the site (CTDEP, 1998).

Known or

Suspected Releases: There is no documentation of a chemical release from the silos (TRC,

1993).

AOC #8: East Aurora Street Warehouse

Description:

This warehouse contains the main hazardous waste storage area, the spot-check QA/QC area, two loading docks and the finished product storage area (CTDEP, 1998). The entire warehouse has concrete walls and epoxy coated concrete floors which are sloped toward the interior of the building into containment sumps. Material collected in the

Areas of Concern Page 4

sumps can be released to the WWTS or containerized. Approximately 77,000 gallons of hazardous waste can be stored in the north end of the warehouse inside a bermed area. The QA/QC area in the shipping and receiving area along East Aurora Street is also equipped with a 3.5" concrete containment berm. Catch basins in the shipping and receiving areas are covered during loading and unloading operations (TRC, 1993). Any spilled materials will be contained by the berms and walls of the building. The warehouse is used to store copper etchant, solder stripper, electroless-nickel solutions, inks and all non-flammable/noncombustible wastes.

Known or

Suspected Releases: There have been no documented chemical releases associated with this

AOC (TRC, 1993).

AOC #9: Pilot Plant

Description:

The Pilot Plant, QA/QC labs and the small packaging area are located in the northeast corner of the Huntingdon Avenue building. The Pilot Plant, which creates small batches of sample products for customers, has an epoxy coated concrete floor which is sloped toward a collection sump. The material in this sump can be containerized or released to the WWTS. Spills occurring in the QA/QC lab and the small packaging area are contained within the walls of the rooms (TRC, 1993). Chemicals handled in these areas include copper etchant, solder stripper, inks, electroless-nickel plating solution, dry batch chemicals and components of these materials (TRC, 1993).

Known or

Suspected Releases: There have been no documented chemical releases associated with this AOC, however the QA/QC labs were cited by the CTDEP for poor waste management (TRC, 1993).

AOC #10: Main Mixing Area

Description:

The main mixing area, located in the center of the Huntingdon Avenue building, was formerly used to blend copper plating solutions, however, it is presently used to repackage dry chemicals into smaller units for sale (TRC, 1993). The area has a dust collector and an epoxy-coated concrete floor with floor drains connected to the WWTS.

Areas of Concern Page 5

Known or

Suspected Releases: There is no documentation of chemical releases from this AOC. Drums

are occasionally washed in this area (TRC, 1993).

AOC #11: Satellite Storage Areas

Description: There are three (3) satellite chemical storage located in the Pilot Plant

(1) and the ink mixing area (2). Each area consists of up to two 55-gallon drums inside a bermed secondary containment area. When full, the drums are transferred to the hazardous waste storage area (TRC, 1993). Waste ink rags, solvents, pigments, miscellaneous plating solutions, solvents, acids and other compatible materials are collected in

these areas.

Known or

Suspected Releases: There have been no documented chemical releases from the satellite

storage areas (TRC, 1993).

AOC #12: Flammable Rack Storage

Description: The flammable rack storage area is located on a concrete pad north of

the Gear Street building. The pad is equipped with a roof and is surrounded on three sides by fiberglass wallboard. Flammable materials such as alcohol, solvents and acetone are stored in this area

(TRC, 1993).

Known or

Suspected Releases: There is no documentation of chemical releases from this AOC (TRC,

1993).

AOC #13: Chemical Storage Area – Gear Street Building

Description: The chemical storage area in the Gear Street building consists of the

less-than-90-day storage area, a flammable storage area and the combustible storage area. Each area has an epoxy-coated concrete floor and is surrounded by a four inch concrete containment berm. There are floor trenches outside the bermed areas which are connected directly to the WWTS. Ink wastes, copper and other sulfates, filters, tin and copper chlorides, acetone, isopropanol, methanol, ether, acetate, anilines and acrylimides have been stored in these areas (TRC, 1993).

Areas of Concern Page 6

Known or

Suspected Releases: There have been no documented chemical releases from this AOC

(TRC, 1993).

AOC #14: Bulk Waste Loading and Storage Areas

Description: This area, located at the northwest corner of the Huntingdon Avenue

building, is used primarily for loading and unloading of copper etchant. There are four bulk copper etchant storage tanks, a loading dock and a drum washing area located in this area. This AOC has an epoxy-coated concrete floor which is sloped toward a collection sump connected to the WWTS (TRC, 1993). A 2'7" concrete containment berm surrounds

the storage tanks (CTDEP, 1998).

Known or

Suspected Releases: On February 10, 1990, a CTDEP inspector cited MacDermid for

allowing drum wash water to enter stormwater catch basins leading to Steele Brook. Water samples collected from the drum washing operation contained 320 ppm copper and 5.6 ppm lead. An injunction was requested to stop this practice. Catch basins near this AOC are currently covered during all drum washing and loading/unloading

activities (TRC, 1993).

AOC #15: Copper Etchant Processing Area

Description: This AOC, located in the western portion of the Huntingdon Avenue

building, houses a 13 tank copper etchant recycling system. The area has a sloped epoxy-coated concrete floor equipped with floor drains connected to the WWTS. Recycled copper etchant is transferred into three (3) finished product storage tanks adjacent to AOC #14 (TRC,

1993).

Known or

Suspected Releases: There is no documentation of a chemical release from this AOC (TRC,

1993).

Areas of Concern Page 7

AOC #16: Ink Manufacturing Area

Description:

The ink manufacturing area, located in the central area of the Gear Street building, contains equipment for the blending of inks. If a spill did occur during this process, it would be contained by the epoxycoated concrete floor and walls of the building and cleaned up with rags. The rags, waste solvents, pigments and polymers are stored in satellite storage areas (AOC #11). Materials associated with this area include polymers, resins, anilines, solvents, powder pigments and acrylimides.

Known or

Suspected Releases: While there is no release directly associated with this AOCs, the

collection sump formerly operating in this area released chemicals to the surrounding soil (see AOC #3). The collection sump has since been

closed (TRC, 1993).

AOC #17: Solder Stripping Reclaim Area

Description:

The solder stripping reclaim area, located in the northwest corner of the Gear Street building, houses a settling tank, two (2) electrolytic cells, two (2) storage tanks and a filter press. The area has a sloped epoxycoated concrete floor with floor drains that are connected to the WWTS (TRC, 1993). According to CTDEP records, the tanks are no longer in use.

Known or

Suspected Releases: There is no documentation of a chemical release from this AOC (TRC,

1993).

AOC #18: Electroless Nickel Area

Description:

This area, located on the west side of the Gear Street building, contains eight process tanks for manufacturing electroless-nickel plating solutions. The area has an epoxy-coated concrete floor sloped toward a floor trench. A wet scrubber is also present to eliminate the ammonia vapors generated in this process (TRC, 1993).

Known or

Suspected Releases: There is no documentation of a chemical release from this AOC (TRC,

1993).

